



Bas	ic	Kno	w	le	dge	/ \$	SOP	

Workmanship Technique

Problem

Improvement

OPL- CRWN-036


## **Description: Prevention of rear door handle spinning**

1 Remove rear door handle





- 2 Using a 6mm square file, file two flats in handle hole as required to get a good snug fit with the Special Location Bracket
- Insert special location bracket into hole, drill and rivet in situ.









Date: 03.05.2016